

1988 Flood Insurance Rate Map
EXHIBIT 2 - ELEVATION REFERENCE MARKS

<u>Reference Mark</u>	<u>FIRM Panel</u>	<u>Elevation (Feet NGVD)</u>	<u>Description of Location</u>
RM 1	02	27.34	Top spindle hydrant near intersection of Cranberry Way and Blueberry Way.
RM 2	02	31.88	North headbolt of hydrant at corner of Point Road and Delano Road.
RM 3	02	44.19	Drilled hole in northwest stone pillar at entrance to Mitton Estate on Point Road.
RM 4	02	29.48	Top spindle hydrant at corner of Hermitage Road and Wareham Road on south side of U. S. Route 6.
RM 5	04	30.43	Drilled hole in concrete header off Station 127+56 at Old Landing Cemetery on U. S. Route 6.
RM 6	04	23.44	Chiseled square in ledge approximately 165 feet east of centerline of Front Street near Marion Town Garage.
RM 7	04	31.83	County disk located at southwest corner of Pleasant Street and Rose Cottage Lane.
RM 8	04	36.22	Top nail in pole No. 2/33, approximately 0.7 mile south of U. S. Route 6 on Converse Road on west side of Converse Road and Cove Street.
RM 9	05	51.52	Chiseled square in rock, 12 feet south of standpipe on Point Road, approximately 1,400 feet south of intersection of Allens Point Road and Point Road.

EXHIBIT 2 - ELEVATION REFERENCE MARKS - continued

<u>Reference Mark</u>	<u>FIRM Panel</u>	<u>Elevation (Feet NGVD)</u>	<u>Description of Location</u>
RM 10	05	12.37	Railroad spike at intersection of centerlines of Rogers Drive and Holly Road.
RM 11	05	42.33	Railroad spike in utility pole No. 6 west of centerline of Cove Circle on water side.
RM 12	05	28.98	Top spindle hydrant at corner of Piney Point Road and Planting Island Road.
RM 13	08	22.70	Top railroad spike in 16-inch oak tree at northwest corner of Seaside Lane and Converse Road.